
TOWN HALL

I JULY 2019

GOOD NEWS, AND A PROBLEM

- Operating expenses have been flat over 5 years
- Street repairs are on schedule, on budget, completing in 2020
 - \$50 street fee scheduled to end Aug 2020

• Issue emerging – Roof repairs have escalated beyond reserves



CRICKET

A cricket is a ridge structure designed to divert water on a roof around the high side of a chimney or the transition from one roof area to another




CRICKET

A cricket is a ridge structure designed to divert water on a roof around the high side of a chimney or the transition from one roof area to another



REPAIRED, AND IDENTIFIED

- Repaired, CRICKET
- Repaired, OTHER
- To Be Repaired



IF WE ACT NOW, WE CAN MINIMIZE DAMAGE

One Time Payment

No house painting 2020

No house painting 2020

						5 Y
Year s	tarting:	(Current)	9/1/2019	9/1/2020	9/1/2021	Av
One T	me Fee		\$2,128			
Monthly Fee		\$280	\$280	\$297	\$306	
Street Fee		\$50	\$50			
Mont	nly Total	\$330	\$330	\$297	\$306	\$35
Month	ly Fee	\$280	\$362	\$320	\$330	
Street	Fee	\$50	\$50			
Mont	nly Total	\$330	\$412	\$320	\$330	\$35
Month	ly Fee	\$280	\$287	\$343	\$350	
Street	Fee	\$50	\$50			
Mont	nly Total	\$330	\$337	\$343	\$350	\$35

THANK YOU